


**To:** Peterson, Cynthia[Peterson.Cynthia@epa.gov]  
**From:** Schmittiel, Paula  
**Sent:** Fri 5/22/2015 5:40:47 PM  
**Subject:** Photo captions



I just realized that I sent these from my i-Pad and forgot to label them. I'll list them here in order of email and in order of appearance in email. Sorry about that.

**1<sup>st</sup> email:** 1. Looking down on the Animas river flood plain by Eureka townsite from road up Eureka Gulch

2. Same thing – just slightly different angle.

3. Columbia Mine (?) –at Animas Forks

4. At Animas Forks area

**2<sup>nd</sup> email:** 1. Pretty view near Animas Forks

townsite 2. Old Sunnyside Mill (or is the name May Flower Mill??) above Eureka

Howardsville 3. Kittmack Tailings along the Animas River between Eureka and

**3<sup>rd</sup> email:** 1. Looking at May Flower Mill with capped tailings to left of mill and river with mineralized outcropping in foreground

2. Red & Bonita mine with discharge flowing down front face – some of the white is aluminum that has crusted over.

3. Alluvial wetlands adjacent to Cement Creek that has been destroyed by the discharge from the R/B.

forground. 4. Another view point of destroyed wetlands with discharge pipe at right

**4<sup>th</sup> email:** 1. Gold King Mine  
2. Discharge from Gold King Mine  
3. Same as #2

**5<sup>th</sup> email:** 1. Animas River below Silverton in the canyon – notice the red staining of rocks at edge of river.

Paula Schmittiel

Remedial Project Manager

U.S. Environmental Protection Agency

1595 Wynkoop St.

Denver, CO 80202

Office: 303-312-6861

Fax: 303-312-7151

Cell: 720-951-0795